

Vehicle Inspection Protocol

Germany

INSP-20261004225138-703e0862-8f2d-4a13-8910-c1b644f32dbc

05.10.2026 00:46 | —

VEHICLE

Demo Camper (DE)

CONTACT

Demo Kund

Departure and return

Departure on 04.10.2026 22:59

Source inspection: 9309a4d9-4efd-44a5-9201-599b56daa6ea

Check current mileage, fuel/charge and condition anew. Both points in time record observations; the comparison does not determine fault or costs.

Section	At departure	At return
Exterior	OK	Attention
Interior	OK	OK
Glass	OK	OK
Lights	OK	OK
Tires	OK	N/A
Documents	OK	OK
Accessories	OK	OK
Fuel / Charge	OK · 75%	N/A
Odometer	OK · 41200 km	OK · 41320 km

DAMAGES AND PHOTOS AT DEPARTURE

Front bumper · Scratch · —



Front bumper

New return damages and photos follow in their own section.

Checklist

Section	Status	Note
Exterior	Attention	—
Interior	OK	—
Glass	OK	—
Lights	OK	—
Tires	N/A	—
Documents	OK	—
Accessories	OK	—
Fuel / Charge	N/A	—
Odometer	OK	— 41320 km


Damages

Zone	Type	Severity	Note	Photos
—				


Summary

—

Signatures



Inspector



Customer